

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER
AECOM'S ASH POND VISUAL SITE INSPECTION REPORT - 2023**

Documented to meet 257.83(b)(5)

DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
Three erosion rivulets upslope from the northern toe of the buttress slope.	Area was filled, regraded and then seeded and strawed to re-establish vegetation.
One erosion rivulet upslope from the northern toe of the buttress slope	Area was filled, regraded and then seeded and strawed to re-establish vegetation.
One animal burrow midslope, adjacent to the right abutment	Animal burrow filled with soil, compacted, and re-seeded
One stormwater catchment basin discharge pipe subsurface pipe joint separation	Separated pipe joint repaired. Area of repair backfilled with new soil, re-seeded, and mulched