

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER
AECOM'S EAST ASH POND VISUAL SITE INSPECTION REPORT - 2017**

Documented to meet 257.83(b)(5)

	DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
1	Minor erosion rills on embankments.	Areas have been regraded.
2	An ash pile within the footprint of the pond is above the embankment crest elevation.	Pile has been leveled and is no longer above the crest elevation.